

# Resetting the LNB Offset on a SR2000Pro Stream Decoder

Some stream decoders may lose lock on the satellite carrier once the carrier is switched to the BuNOC. Stations that experience this problem will need to reset their decoder's LNB offset.

Steps for performing this task are as follows:

**Step 1:** In the web GUI on the decoder, go to "DVB Carrier:LNB Attributes."

**Step 2:** If offset is anything but "0", click "Reset LNB offset" button on left navigation bar.

**Step 3:** Click "Send Changes" to activate the changes in the decoder. You're good to go!

2/17/2010